

Take good care of your Plasson control box

It is recommended that control boxes are serviced every 12 months or 200 hours of operation

Frequent servicing of your control box reduces the risk of operational problems interrupting the work flow and costing you money.

Plasson Australia service control boxes in their local facilities.

The control box will be evaluated and a quote sent for any repairs required.

A standard service includes:

- Recalibration
- Installation of latest software
- Inspection and testing of all components
- Calibration Certificate

omponents

Oting the Resource of the Resource

If your control box is now due for service, complete the following "Service Request Form" and return to service@plasson.com.au